

The arm shall have a cast aluminum fitter welded to the top of the arm(s) for attaching the fixture. The fixture shall be mounted with three stainless steel bolts through the top of the arm fitter into the fixture. The attachment point shall have a silicone pad for sealing the fixture to arm connection.

Mounting hardware and J-box by others.

MAL Matte Aluminum MG Medium Grey AGN Antique Green LG Light Grey RAL Premium Color CUSTOM * * Contact Factory

VBU Verde Blue

CRT Corten

WH Arctic White

BLT Matte Black

DGN Dark Green

TT Titanium


Dark Bronze

WDB Weathered Bronze

MDB Bronze Metallic

BI Black

DB



Note: Back plate is welded to the arm.

WMA7

JOB

TYPE NOTES -

