
TPLB-ARA3 - Twin Parallel Luminaire Bracket

MOUNTING BRACKETS ACCESSORY





Mounting Notes:

- 1. Position twin bracket to pole with cover side up.
- 2. Using supplied hardware: (2) 1/2-13 bolts, (4) split washers, (4) flat washers, and (2) nuts, secure bracket to pole and bring wiring into bracket.
- 3. Position fixtures to each side of the bracket and secure with hardware supplied with fixture.
- 4. With wiring complete to fixture, secure (2) end plates to each end of bracket with (2) 10-24 screws.
- 5. Secure gasket and cover to top opening of bracket with (2) 10-24 screws.

Shipping Package Contents: Twin Bracket (1)

End Plate (2) 1/2-13 Bolt (2) 1/2 Split Washer (4) 1/2 Flat Washer (4) Gasket (1) Cover (1) 1/2-13 Nut (2)

10-24 Screw (4)

Material: Steel Finish: Powder Paint Weight: 41 lbs

EPA: 1.8 ft²

Spaulding Lighting 701 Millennium Blvd Greenville, SC 29607 Technical Support: (864) 678-1000 Fax: (864) 898-1065 www.spauldinglighting.com Catalog Number: TPLB-ARA3-XX

Instruction Sheet: 93066045